

**Picture A.**

Crack in the foundation corner of house



**Picture B.**

Existing retaining wall near the house and slope going down to the existing seawall.



**Picture C.**

Existing retaining wall and staircase going down to the existing seawall



**Picture D.**

Upper section of the staircase going down.

Steps vary in step height from 13" to 1" (Steps vary in width 15" width to 22")

